
# 2013 City of Owosso S. Washington St. Corridor Study



Jessica Wendlandt Jia Zhuang Ken Hunter Ryan Musser Sam Schultz <sub>MICHIGAN STATE</sub>



# Introduction



www.baker.edu


Our goal is to enhance the corridor between Baker College and downtown Owosso by focusing on the built environment including connections, gateways, and the streetscape.



# **Key Players**


- Adam Zettel Assistant City Manager, City of Owosso
- Justin Horvath CEO, Shiawassee Economic Development Partnership
- David Shorter Executive director, Steam Railroading Institute
- Bill Voorheis Owner, Washington Business Park
- David Wakeland Owner, Wakeland Oil
- Rex LaMore Professor, URP Practicum
- Zenia Kotval Professor, URP Practicum





LOCATION MAP OF SHIAWASSEE COUNTY

#### LOCATION MAP OF THE CITY OF OWOSSO



# The Boundaries

The Washington Street Corridor stretches from Baker College all the way North to the Shiawassee River. The corridor is a gateway to the downtown from the state highway M-71, and connects Baker College to the downtown. The area consists of residential, commercial, industrial and institutional uses.





www.wegoplaces.com

Baker College

The Steam Railroading Institute

# Scope of Work

- Develop Methodology
- Compile Socio-economic profile and Market Analysis
- Inventory and Assessment of corridor
- Stakeholder Input
- Develop and propose Recommendations



# Methodology

- Collect data from the U.S. Census and offer appropriate sources in order to compile a socio-economic profile.
- A walk ability study as well as a streetscape assessment has been completed based upon best practices and case studies.
- Conduct multiple onsite observations supplemented with photo documentation.
- Received local stakeholder input from business owners, government officials, Baker College administration, and corridor residents.




# Socioeconomic Profile Highlights


• 2010 Owosso Population: 15,194

- •Demographics
- •Economic
- •Housing

Washington Street Corridor Highlights




# Age Distribution




10


# **Educational Attainment**



# **Unemployment Rate**



## **Poverty Rate**



# Market Analysis

- What types of industry are on the Washington Street Corridor?
- What types of businesses employ the most people?
- How people spend their money?
- Where is there demand or sales potential?



#### Streetscape, Roadway and Housing Inventory & Assessment Zoning Map

#### **Criteria:**

Sidewalk ConditionsSidewalk Width

•Obstructions

- •Handicap Accessibility
- •Signage / Wayfinding
- Amenity Zone / LandscapingLighting

•Bike Lanes

- •Traffic Flow (Lanes / Speed Limit)
- •Street Parking
- Housing Conditions
- •Setback (residential)



#### Signage/Wayfinding Criteria

<i>c</i> .	Poor - Little to no signage in the area; existing signage either damaged or worn.
	Fair - Some signage exists and is visible from multiple modes of transportation
	Good - A full wayfinding system has been implemented; signage is completely visible from all modes of transportation

Example Score: Poor




Example Score: Good



# Assessment of Signage/Wayfinding


Signage		
West Side of S Washington - Gute to Ridge	Poor	
East Side of S Washington - Gute to Ridge	Poor	
West Side of S Washington - Ridge to Stewart	Poor	
East Side of S Washington - Ridge to Stewart	Poor	
West Side of S Washington - Stewart to Universal	Fair	
East Side of S Washington - Stewart to Monroe	Fair	
West Side of S Washington - Universal to Milwaukee	Poor	
East Side of S Washington - Monroe to Corunna	Fair	
West Side of S Washington - Milwaukee to Howard	Good	
East Side of S Washington - Corunna to Howard	Fair	
West Side of S Washington - Howard to River	Poor	
East Side of S Washington - Howard to River	Good	
North Side of Corunna Ave – S Park St to Washington St	Fair	
South Side of Corunna Ave – S Park St to Washington St	Good	



KEY

#### Block-By-Block Analysis EAST SIDE OF S WASHINGTON - CORUNNA TO HOWARD





#### **Block Results**

#### East Side of S Washington - Corunna to Howard

Sidewalk Conditions	Good
Sidewalk Width	5 ft
Obstructions	Poor
Handicap Accessibility	Poor
Signage/Wayfinding	Fair
Landscaping	Poor
Lighting	Fair
Bike Lane	Poor
Traffic Flow	25 mph
Street Parking	Poor
Housing Conditions	Good
Setback	Small

### Commercial/Institutional/ Industrial Inventory & Assessment

The purpose of the commercial and housing inventory is to examine the current land uses adjacent to the Washington St corridor and to analyze their relationship with the street.

#### • Criteria:

- Exisitng / Future LandUse
- Setback
- Façade
- Access Management



#### Setback Criteria

Setback
---------

Example Score: Large



Example Score: Small




Elks Lodge

Wakeland Oil Offices

#### Assessment of Setback

Setback		
Riverside Quality Auto	Small, Large	
Steam Railroading Institute	Small	
Washington Business Park	Small	
Team Larrivey Properties	Small	
Wakeland Oil Office	Small	
Shell Station	Medium	
Crave Gourmet Cupcakes & Dessert Shop	Small	
Elks Lodge	Large	
Dicks Auto Services	Small	
Clark Fire & Safety	Medium	
Primetime Pizza	Medium	
Dalton Elevator	Small	
Edward Jones	Medium	
Owosso Wesleyan Church	Large	
Baker College Early Learning	Medium	
Crest Printing Inc	Medium	



#### Setback Score

S WASHINGTON ST (M-71)

N.

S WASHINGTON

W HOWARD ST

EHOWARD

E MONROE ST


E STEWART ST

E RIDGE ST

22

#### **Commercial/Institutional/ Industrial Inventory & Assessment** EAST SIDE OF S WASHINGTON - HOWARD TO RIVER





#### Property Assessment



#### Steam Railroading Institute

Current Zoning	Institutional: Private
Future Land Use	Planned Unit Development
Setback	Small
Façade	Poor
Access Management	Poor

#### Intersection Inventory & Assessment Tool

Intersections	Delineation/Connection	Poor - The crosswalks do not have a connection point on the opposing side of the street.
		Fair – The Crosswalks are not marked by paint, or the paint has faded. There are no guidelines for pedestrians.
		Good - The boundaries of crosswalks are marked with thick white lines; pedestrians can locate the crosswalk and stay out of danger from vehicular traffic.
	Crosswalk Signal/Signage	Poor - Crosswalk Signal signage is not present; pedestrians are left guessing as to when it is safe to cross the intersection.
		Fair - Crosswalk signage has been implemented for some directions of pedestrian traffic.
		Good - Pedestrian Signal/Signage has been implemented for crosswalk for each direction of traffic

## Delineation/Connection

Example Score: Poor

#### Example Score: Good





## Crosswalk Signal/Signage

Example Score: Poor

#### Example Score: Good





## Example of CORUNNA AVE AND S WASHINGTON ST

- CROSSING CORUNNA AVE
  Delineation/Connection: Good
  Crosswalk Signal/Signage: Good

CROSSING WASHINGTON ST
 Delineation/Connection: Good
 Crosswalk Signal/Signage: Good





# Stakeholder Input

- Individual meetings with stakeholders
  - Higher Education officials
  - Local Planning professional
  - Local Business owners
- Received input regarding existing conditions, and vision for the future.



# Recommendations

The vision for the S Washington Street Corridor embodies the combined efforts of residents, business leaders, land owners, corridor users, the Baker College. These stakeholders are unified in the desire to revitalize the corridor and develop a welcoming gateway that reflects the character of Owosso.




#### **Recommendations Example** EAST SIDE OF S WASHINGTON - CORUNNA TO HOWARD



# Future

#### Recommendations Example EAST SIDE OF S WASHINGTON - HOWARD TO RIVER

Current



32



# Short-term

## • 3 month -1 year:

- Road Striping
  - Bike Lanes
  - Crosswalks
  - On-Street Parking
  - One lane for southbound traffic
- Landscaping Improvements
  - Trees
  - Street planters
  - Trash cans



33

# Mid-Term

#### • 3 year:

- Lighting: Installation of lamp posts consistent with entire corridor
- Repair/Removal of obstructions on sidewalk
- Clean up of abandoned lots



# Long-Term

#### • **5-10** year:

- Achieve compliance with ADA Accessibility Guidelines
- Commercial property façade improvements



35



www.spartan-football.com

# **Questions?**

# **THANK YOU!**



www.themajors.net